








LACK




Design and Quality
IKEA of Sweden




4x




4x




4x



4x




1x





153551

4x


1




153551





2






3








4




5



6



7



8

